


WAYBILL: FES1162612446

RECEIVED: lindo

TIMESTAMP: 15-03-2018 14:17

* COPY *



FESTO

RCL FOODS CONSUMER (PTY) LTD - P1
FINANCE SHARED SERVICES - CREDITORS
RAINBOW GATE 1 HAMMARSDALE MAIN RD
HAMMARSDALE
3699

37x37x20 = 4 kg
20x15x24 = 2 kg



Delivery note
1162612446

For all requests please indicate customer number and delivery note number			
Customer number 0017053943	Delivery note number 1162612446	Our Order number 2170619807	Festo consultant Karan Maharaj
Shipping type 18 / Process 1		Packed by	Checked by
Sales Office 1704 Kwazulu Natal		Time 15:41	

Date
14 March 2018

No of pages
1 of 2

Your order 4500344781 of 05.03.2018 by Levona Pillay

Contact Department
Sales Interaction Dept.
Phone ++27 (0) 86 00 33786
Fax ++27 (0) 87 94 33786
sales.za@festo.com

Reg. No. 1973/003776/07
VAT Reg. No. 4350101004

Directors:
Mr. KIM HECKL* Mr. J Naumburger*
H.C. Wallace (Managing)
*German

Regional Offices at:

- Bloemfontein
- Cape Town
- Durban
- East London
- Polokwane
- Port Elizabeth
- Pretoria
- Vereeniging

Description	Part number	Qty.	Net price per unit
1,5-Si tubing	152588	45	
1,25-Si tubing	152587	30	
0030 RED Lubricating oil Material replaced by: 12064403	23035083	2	
Item 0040 QS-1/4-8 Push-in fitting	153005	4	
Item 0050 QS-1/4-10 Push-in fitting	153007	1	
Backorder item: our order item number 0060 D-1/4I-1/2A Reducing nipple Warning: Product to be discontinued, only available as series product during the course of 2018. Do not use for new designs.	197633		Estimated delivery:

Partial delivery
Number of packages 1
Total weight 3,575 KG

Festo (Pty.) Ltd.
Durban
21 Buro Centre, 55-57 Buro
Mayville
P.O.Box 30060, 4058
Republic of South Africa
Phone +27(0)31-208-9116
Fax +27(0)31-209-4646

Your signature signifies that the goods were sold in accordance with our conditions of sale, which are printed on the reverse side hereof.
Interest at 2% per month will be charged on all overdue accounts.
Goods may only be returned for credit by prior arrangement and are subject to handling charges unless due to supplier error.